

REBA MANAGEMENT  
P.O. Box 5686 Hilton Head island, SC 29938

March 11, 2008

In December 2007 we installed 110 Fresh-Aire UV light systems. We used the 2 year lamps with 2 lamps in each system. The lamps and the power supply are installed inside the air handler, one lamp on each side of the evaporator. Since we installed the UV lights, the evaporators are remaining much cleaner than the evaporators that do not have UV lights. In addition, the smell of mold and mildew in the units has been greatly reduced. I would recommend this product to anyone who is interested in improving their indoor air quality.

Robert Lehman  
Asst. Director of Engineering